

Высокоточные контроллеры серии МС

КАРТА ЗАКАЗА

Заполненный опросный лист необходимо направить по электронной почте orm@nt-rt.ru

Архангельск (8182)63-90-72
Астана +7(7172)727-132
Белгород (4722)40-23-64
Брянск (4832)59-03-52
Владивосток (423)249-28-31
Волгоград (844)278-03-48
Вологда (8172)26-41-59
Воронеж (473)204-51-73
Екатеринбург (343)384-55-89
Иваново (4932)77-34-06
Ижевск (3412)26-03-58
Казань (843)206-01-48

Калининград (4012)72-03-81
Калуга (4842)92-23-67
Кемерово (3842)65-04-62
Киров (8332)68-02-04
Краснодар (861)203-40-90
Красноярск (391)204-63-61
Курск (4712)77-13-04
Липецк (4742)52-20-81
Магнитогорск (3519)55-03-13
Москва (495)268-04-70
Мурманск (8152)59-64-93
Набережные Челны (8552)20-53-41

Нижний Новгород (831)429-08-12
Новокузнецк (3843)20-46-81
Новосибирск (383)227-86-73
Орел (4862)44-53-42
Оренбург (3532)37-68-04
Пенза (8412)22-31-16
Пермь (342)205-81-47
Ростов-на-Дону (863)308-18-15
Рязань (4912)46-61-64
Самара (846)206-03-16
Санкт-Петербург (812)309-46-40
Саратов (845)249-38-78

Смоленск (4812)29-41-54
Сочи (862)225-72-31
Ставрополь (8652)20-65-13
Тверь (4822)63-31-35
Томск (3822)98-41-53
Тула (4872)74-02-29
Тюмень (3452)66-21-18
Ульяновск (8422)24-23-59
Уфа (347)229-48-12
Челябинск (351)202-03-61
Череповец (8202)49-02-64
Ярославль (4852)69-52-93

Ordering information

Motion control unit

Name	Model
2 axes motion control unit.	CS1W-MC221-V1
4 axes motion control unit.	CS1W-MC421-V1

Accurax G5 servo drive cables

Description	Connect to		Model
Axis control cable (1 axis)	Motion control units CS1W-MC221 (1 cable needed) CS1W-MC421 (2 cables needed)	1 m	R88A-CPG001M1
		2 m	R88A-CPG002M1
		3 m	R88A-CPG003M1
		5 m	R88A-CPG005M1
Axes control cable (2 axis)	Motion control units CS1W-MC221 (1 cable needed) CS1W-MC421 (2 cables needed)	1 m	R88A-CPG001M2
		2 m	R88A-CPG002M2
		3 m	R88A-CPG003M2
		5 m	R88A-CPG005M2

I/O terminal block and cables

Description	Connect to motion control unit		Model
Terminal block	CS1W-MC221	-	XW2B-20J6-6
	CS1W-MC421	-	XW2B-40J6-7
Cable form PLC unit to terminal block.	CS1W-MC221 CS1W-MC421	1 m	XW2Z-100J-F1

Computer software

Specifications	Model
CX-One	CX-One

ALL DIMENSIONS SHOWN ARE IN MILLIMETERS.

To convert millimeters into inches, multiply by 0.03937. To convert grams into ounces, multiply by 0.03527.